



**CO-ORDINATION OF NOTIFIED BODIES
PPE-Directive 89/686/EEC + amendments**

CNB/P/10.045
Revision 01
Language: E

RECOMMENDATION FOR USE

Number of pages: 1	Date: 08/06/98	Approval by :	Approved on :
Origin: INESCOP		<input checked="" type="checkbox"/> Vertical Group	27/06/00
		<input checked="" type="checkbox"/> Horizontal Committee	13/09/11
		<input type="checkbox"/> Standing Committee	
Question related to:	EN/prEN:	Other:	
Annex:	Article:	Clause:	
Key words: cleats – sole: firemen's footwear - outsole			
Question: According to the current standard for firemen's footwear, continuous transverse holes shall not be found in the outsole. Does this requirement also affect the waist?, if so it should be expressly stated.			
Solution: There is no requirement for the cleat in the waist area.			
Sent to: <input checked="" type="checkbox"/> members of the VG <input type="checkbox"/> other(s) VG <input checked="" type="checkbox"/> HC (2) <input checked="" type="checkbox"/> TC (3) <input type="checkbox"/> SC (4) <input type="checkbox"/> other (5)			

(1) Essential safety requirement
(2) HC = horizontal committee

(3) N° of CEN/TC (Secretary & Chairman)
(4) EEC Standing Committee 89/392

(5) To be specified