



**CO-ORDINATION OF NOTIFIED BODIES
PPE-Directive 89/686/EEC + amendments**

CNB/P/10.113
Revision 01
Language: E

RECOMMENDATION FOR USE

Number of pages: 1	Date: 16/03/07	Approval by :	Approved on :
Origin: INESCOP		<input checked="" type="checkbox"/> Vertical Group	16/03/07
		<input checked="" type="checkbox"/> Horizontal Committee	13/09/11
		<input type="checkbox"/> Standing Committee	
Question related to: Radiant heat	EN 15090	Other: _____	
Annex:	Article:	Clause: _____	
Key words: Radiant heat. EN 15090 Clause 6.3.2, 7.2			
Question: Clauses 6.3.2 and 7.2 say that all different materials, including seams and closing systems shall be tested. However we have found some cases where this has not been possible for several reasons: - Collars of 2-3 cm. Not big enough to obtain a test piece. - Coverings of the toecap, etc The standard says that the test piece shall include any lining or padding and shall be tested in the same orientation than in the footwear. This is not possible in these cases, because any composition manufactured in a different way outside the footwear might give different results (t_{24}).			
Solution: In these cases. Situation 1 – Where there is a different material that is too small to test – carry out the radiant heat test on a composite assembly cut from the footwear. Situation 2 – Where an additional interlayer is present in the construction (for instance in the area of the toe cap), it is not necessary to carry out the radiant heat test as the result will only be better			
Sent to: <input checked="" type="checkbox"/> members of the VG <input type="checkbox"/> other(s) VG <input type="checkbox"/> HC (2) <input checked="" type="checkbox"/> TC (3) <input type="checkbox"/> SC (4) <input type="checkbox"/> other (5)			

(1) Essential safety requirement
(2) HC = horizontal committee

(3) N° of CEN/TC (Secretary & Chairman)
(4) EEC Standing Committee 89/392

(5) To be specified