



CO-ORDINATION OF NOTIFIED BODIES  
PPE-Directive 89/686/EEC + amendments

CNB/P/10.003  
Revision 02  
Language: E

RECOMMENDATION FOR USE

Number of pages: 1	Date: 21/02/96	Approval by :	Approved on :
Origin: Horizontal Committee		<input checked="" type="checkbox"/> Vertical Group	21/02/96
		<input checked="" type="checkbox"/> Horizontal Committee	13/09/11
		<input type="checkbox"/> Standing Committee	
Question related to:	EN/prEN: EN 344	Other:	
Annex:	Article:	Clause:	
Key words: stiffener - lining quarter - test			
Question:  When the stiffener take the place of lining quarter, what test must be performed?			
Solution:  Stiffeners are not linings. They are not to be tested.			
Sent to: <input checked="" type="checkbox"/> members of the VG <input type="checkbox"/> other(s) VG <input checked="" type="checkbox"/> HC (2) <input checked="" type="checkbox"/> TC (3) <input type="checkbox"/> SC (4) <input type="checkbox"/> other (5)			

(1) Essential safety requirement  
(2) HC = horizontal committee

(3) N° of CEN/TC (Secretary & Chairman)  
(4) EEC Standing Committee 89/392

(5) To be specified